Škoda

VIN: TMBLJ7NUXJ2027789 **Diesel**

Generat pe **2025-01-31 10:31**

Odometru
✓ Arată bine

Statut legal
✓ Arată bine

Daune
⚠ Necesită atenție

+31

Surse de date
Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

Nu s-au găsit probleme
Nu am găsit nicio înregistrare că vehiculul a fost furat.

Notă
Verificarea bazei de date a poliției privind vehiculele furate finalizată în **9 țări**: +3

Iată ce am verificat:

Căutat drept furat
✓ Nu s-a găsit nici o înregistrare

Furat în trecut
✓ Nu s-a găsit nici o înregistrare
Starea actuală necunoscută

Furat în trecut
✓ Nu s-a găsit nici o înregistrare
Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**

- **România**
- **Cehia**
- **Italia**

Statele Unite ale Americii | Lituania | Slovacia


Slovenia | Danemarca | Suedia

Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

- Ultimul kilometraj cunoscut: 153.000 km
- 1 înregistrare a kilometrajului



Înregistrările odometrului

2023-05	**153.000 km**

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

Nu s-au găsit probleme
Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal

Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice

Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

Ai grijă!
Acest vehicul a fost avariat

Notă
Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2023-05 **Germania**

Daune

Costul estimativ al reparațiilor
2.001 RON – 6.000 RON

Cauza posibilă a daunelor
Necunoscut

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

Nu s-au găsit probleme
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă
Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice

Producător
Škoda

Capacitate cilindrică
2 l

Putere motor
110 kW (148 cp)

Tip combustibil
Diesel

Cutie de viteze
Automată

Nr. uși
4

Amplasarea volanului
Volan pe stânga

Nr. cilindri
4

Echipare

Cum a fost primit de la producător

0A2
4 DOORS

0AF
FRONT STABILIZER

0B1
WHEELBASE

0BD
REAR STABILIZER

0F5
FUEL SYSTEM FOR DIESEL ENGINE

0IJ
INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0
WITHOUT ALTERNATIVE DRIVE SYSTEM

0N4
4-LINK REAR SUSPENSION

0P0
REAR EXHAUST TAILPIPE (STANDARD)

0TA
WITHOUT FLOOR MATS

0VC
INFORMATION KIT IN GERMAN

0Y1
STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1KE

DISK BRAKES IN REAR

1L1

AIR CLEANER FOR DUSTY REGIONS

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PF

STANDARD WHEEL BOLTS

1Q0

WITHOUT MASS DAMPER FOR STEERING WHEEL

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1X1

FOUR WHEEL DRIVE

1XX

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL W/ TIPTRONIC

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2B1

ADDITIONAL EXTERIOR NOISE SUPPRESSION

2H0

WITHOUT "DRIVE SELECT"

2JB

STANDARD BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2V5

FRESH AIR INTAKE SYSTEM WITH COMBINATIONFILTER

2W6

FUEL FILLER CAP

2WA

WITHOUT ADDITIONAL TIRES

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3CX

NET PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3GG

PLANE REAR CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3LD

DOOR AND SIDE TRIM PANEL

3N7

MOUNTING FIXTURE IN LUGGAGE COMPARTMENT

3NZ

UNSPLIT REAR SEAT BENCH UNSPLIT, SPLIT FOLDING BACKREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S2

BLACK ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3W3

SPECIAL INTERIOR NOISE SUPPRESSION

3X0

WITHOUT LOAD-THROUGH HATCH

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4E2

TAILGATE/TRUNK LID RELEASE FROM INSIDE (ELECTRICALLY)

4GX

WINDSHIELD IN HEAT-INSULATING GLASS, HEATED

4H3

MANUAL CHILD SAFETY LOCK

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITHOUT SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4LC

CONTROLS FOR RADIO AND TELEPHONE

4P6

REAR FLOOR PANEL MODULE, TYPE 7

4R4

POWER WINDOWS WITH COMFORT OPERATION ANDCIRCUIT BREAKER

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZE

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J3

ROOF SPOILER

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MC

DECORATIVE INSERTS

5N4

FOLDING GRAB HANDLES, MULTI-PIECE

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

5ZF

FRONT HEAD RESTRAINTS

6E3

CENTER ARMREST IN FRONT

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE GUARD)

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6KD

RADIATOR GRILLE

6M3

TRUNK NET

6N0

WITHOUT MUD FLAP

6PB

WITHOUT HAND BRAKE LEVER HANDLE

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SE

LUGGAGE COMPARTMENT FLOOR COVERING IN FLAT NEEDLE-PUNCHED NONWOVEN

6T0

WITHOUT INTERIOR LIGHT IN FOOTWELL

6XK

EXTERIOR MIRRORS, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7LY

VEHICLE CLASS DIFFERENTIATION -5EP-

7M0

PLASTIC SCUFF PLATES IN DOOR APERTURES

7MM

EMISSION STANDARD EU6 PLUS

7N2

SPECTACLE STORAGE COMPARTMENT/BRACKET

7P4

MANUALLY ADJUSTABLE LUMBAR SUPPORT IN FRONT SEATS

7RE

SD CARD (EUROPE)

7UF

NAVIGATION SYSTEM - STANDARD

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y0

WITHOUT LANE CHANGE ASSIST

8G1

HIGH-BEAM CONTROL

8GV

ALTERNATOR 180 A

8IE

HALOGEN TWIN HEADLAMPS AND SEPARATE LED DAYTIME RUNNING LIGHTS

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q1

HEADLIGHT RANGE ADJUSTMENT

8QL

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8RM

8 SPEAKERS (PASSIVE)

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8W1

WASHER FLUID LEVEL INDICATOR

8WB

FRONT FOG LAMPS

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9IH

COMFORT TELEPHONY WITH WLAN AND LTE AND WIRELESS CHARGING

9JA

NON-SMOKER'S PACKAGE

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"COLOUR"

9T1

HEATED WASHER NOZZLES IN FRONT

9TC

ADDITIONAL REFLECTORS (DOOR AREA)

9U1

BRAKE PAD WEAR INDICATOR

9WT

MIRRORLINK

9Z0

OPERATING VOLTAGE 12 V

A64

CATEGORY 4

A8D

LUXURY EQUIPMENT

AV1

DRIVING ON THE RIGHT

B01

TYPE APPROVAL COUNTRY GERMANY

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C03

OPERATING PERMIT, ALTERATION

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI COMMON RAIL; B.ENGINE T37/T6F TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF0

WITHOUT ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EV0

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GM1

STANDARD ELECTRONIC ENGINE SOUND

I21

TIRES 225/50 R18 95W LOW ROLLING RESISTANCE

I8F

STANDARD RADIO (GEN2 GP)

IA0

WITHOUT BRACKET

J0V

BATTERY 420 A (70 AH)

K8P

MPV

KA1

WITH REAR VIEW CAMERA SYSTEM (TYPE 1)

KK3

REFRIGERANT R1234YF

L03

SUSPENSION RANGE 03 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N3C

SEAT TRIM COVERS IN FABRIC

ND0

WITHOUT ADAPTER

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q2J

COMFORT SEATS IN FRONT

QE5

STORAGE COMPARTMENT PACKAGE 3

QG1

SERVICE INTERVAL PROLONGATION

QH1

VOICE CONTROL

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ3

CHROME PACKAGE (TYPE 2)

QK1

WITH MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

TS1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.B

U42

ALLOY WHEELS 7J X 18

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UC7

REAR SHOCK ABSORPTION, SUSPENSION WITH INCREASED RIDE HEIGHT

UG1

HILL START ASSIST

UH2

PARKING BRAKE

UI5

ELECTRIC INTERFACE FOR EXTERNAL USE, USB (IPOD-CAPABLE)

UK1

STANDARD REAR SEAT RELEASE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY

Cronologie

S-a găsit 1 înregistrare

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2023-05 **Germania**

Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

+31

Surse de date
Am verificat 900+ de surse de date în **35 de țări**